






Assembly Instruction


BER101D Work desk





Panel No	Panel Sizes	Quantity
1	968*433*16	1
2	968*433*16	1
3	118*432*16	2
4	118*432*16	2
5	1850*350*18	1
6	1850*350*18	1
7	968*210*16	1
8	968*240*16	1

Panel No	Panel Sizes	Quantity
9	968*330*16	1
10	968*304*16	1
11	402*113*16	1
12	356*80*12	1
13	400*80*12	1
14	400*80*12	1
15	366*398*5	1
16	968*80*16	1



Fittings



A=52



B=36




C=52



D1=56



D2=8



F2=2



M6*25

G1=4



H=1



N=1



O=8



P=8









U=1






M3, 6*12



V1=8




2




3





4




5





6




7





10



11

